



turf products




157 Moody Road • Enfield, CT 06082
Tel: (800) 243-4355 • Fax: (860) 763-5550
www.turfproductscorp.com

BOARD EXCHANGE PROGRAM

Technology has done wonders to improve the efficiency and effectiveness of our daily lives, and central irrigation control is one important example. However, when problems occur and your system is damaged, what was one day a tremendous convenience quickly can become a source of panic.

Toro® developed the Board Exchange Program to resolve problems before your site suffers any damage. The BEP is designed to meet our customer's needs for fast and dependable supply of electronic circuit boards when a "downtime" situation demands action.

The Board Exchange Program provides quick, easy and dependable replacement of damaged circuit boards with a Certified Toro Refurbished Board. A phone call to Turf Products at (800) 296-7442 or (800) 243-4355 will have the boards on their way to you in a minimal amount of time so you can get your site operating again as soon as possible.



GENUINE TORO PARTS

With the Board Exchange Program, you get the advantage of Toro's expert technicians and state-of-the-art facilities. Your replacement parts will benefit from the same commitment to continuous improvement and engineering expertise that is put into the manufacturing processes. Genuine Toro Parts will outlast and outperform aftermarket products . . . We guarantee it!

**E-Series™
OSMAC**



**Network
LTC® Plus**



BEP PROVIDES:

- Immediate replacement of damaged boards
- Low, fixed prices
- No memberships or annual fees
- Engineer product improvements built into repairs
- 1-year warranty on replacement boards

BOARD EXCHANGE PRODUCT LISTING:

PRODUCT	PART #	DESCRIPTION
Network 8000	R91-1280	Timing Mechanism
	R35-6166	Power Supply
	R35-6326	Pump Module
	R35-8502	Valve Board
	R35-7899	Surge Board (SPU)
	R89-8100	Triac Board
Network VP	R102-3497/3.0	Timing Mechanism Ver. 3.0
	R102-3497/2.01	Timing Mechanism Ver. 2.01
	R102-2782	Power Distribution Board
	R102-3015	Pump Module
	R102-2549	Output Module
	R363-4638	Maxon Radio Transceiver
	R102-3125	Radio Adapter Board
VT 3	R35-1077	Timing Mechanism
VT4	R35-6220	Timing Mechanism
OSMAC RDR	RNLN3485	Decoder Board
	RNLN3491A	Triac Board
E-OSMAC	R102-0187	Narrow Band Decoder Board
	R102-2012	Narrow Band RDR Decoder
	R89-9449	Wide Band Decoder Board
	R102-0320	Pump & Common PCB
	R102-2549	8-Output Module
	R102-0318	Output Distribution PCB
	R89-9804	Surge Prot. w/Switches
	R89-9896	Earth Ground PCB
	R89-9894	24 VAC BAR PCB

PRODUCT	PART #	DESCRIPTION
Network LTC 1.1	R91-0537	Timing Mech. with Terminals
	R91-1593	Timing Mech. w/o Terminals
	R91-0777	Modem Board
	R91-1303	Surge Board w/Switches
	R91-1305	Pump/Common Surge Board
	R91-1307	Communication Surge Board
Network LTC 2.0	R89-7169	Timing Mechanism
	R89-6977	Back Plane
	R89-7170	4-Output Module
	R89-7171	Pump/Common Module
Network LTC 4.0	R102-0238	Timing Mechanism
	R102-0681	8-Output Module
	R102-0682	Pump/Common Module
	R102-0612	Distribution Board
	R89-8521	Surge Board w/Switches
	R89-8589	Pump/Common Surge Board
Network Modems	R35-8646	NW8000 Modem (older)
	R89-7519	Standard Modem
	R89-8453	Universal Modem (Radio)

CONDITIONS

- BEP orders can be called in to Turf Products during normal business hours at (860) 253-7856 and will be shipped to you within 24 hours of your order.
- Applicable tax, shipping and handling charges are extra.
- All boards are remanufactured, tested and complete. Cables, covers and connectors are not included in the board exchange and should be removed from your damaged board before it is returned to Turf Products.
- All BEP orders will have a core charge assessed for each item. A prepaid UPS shipping label is included with each order for convenient return of your damaged parts (cores). Damaged boards must be returned within 10 days to have core charge credited.
- Turf Products will replace at no extra charge any board exchange product that fails in normal use within the 12-month warranty period. Turf Products will not, under any circumstances, be liable for incidental or consequential damages. The warranty is not valid for damage to equipment or exchange boards caused by lightning or electrical surges.
- Every effort will be made to have items in stock, however, this does not guarantee availability of all items at all times. Quick return of cores enable Turf Products to maintain higher levels of replacement boards.

OSMAC RDR



**Network
8000®**