



turf products



157 Moody Road • Enfield, CT 06082
Tel: (800) 243-4355 • Parts: (800) 296-7442
www.turfproductscorp.com

BOARD EXCHANGE PROGRAM

Technology has done wonders to improve the efficiency and effectiveness of our daily lives, and central irrigation control is one important example. However, when problems occur and your system is damaged, what was one day a tremendous convenience quickly can become a source of panic.

Toro® developed the Board Exchange Program to resolve problems before your site suffers any damage. The BEP is designed to meet our customer's needs for fast and dependable supply of electronic circuit boards when a "downtime" situation demands action.

The Board Exchange Program provides quick, easy and dependable replacement of damaged circuit boards with a Certified Toro Refurbished Board. A phone call to Turf Products at (800) 296-7442 will have the boards on their way to you in a minimal amount of time so you can get your site operating again as soon as possible.

OSMAC RDR



Network VP



Network LTC® Plus



GENUINE TORO PARTS

With the Board Exchange Program, you get the advantage of Toro's expert technicians and state-of-the-art facilities. Your replacement parts will benefit from the same commitment to continuous improvement and engineering expertise that is put into the manufacturing processes.

Genuine Toro Parts will outlast and outperform aftermarket products . . . **We guarantee it!**

Network 8000®



E-Series™ OSMAC



BEP PROVIDES:

- Immediate replacement of damaged boards
- Low, fixed prices
- No memberships or annual fees
- Engineer product improvements built into repairs
- 1-year warranty on replacement boards

BOARD EXCHANGE PRODUCT LISTING:

PRODUCT	PART #	DESCRIPTION
Network 8000	R91-1280	Timing Mechanism
	R35-6166	Power Supply
	R35-6326	Pump Module
	R35-8502	Valve Board
	R89-8100	Triac Board
	R35-8646	Wireline Modem (RCA Plug)
	R89-7519	Wireline Modem (2 Red Lights)
	R89-8453	Radio Modem (2 Red Lights)
	R35-7899	Surge Board (SPU)
Network VP	R102-3497-4.0	Timing Mechanism Ver. 4.0
	R102-2782	Power Distribution Board
	R102-9124	LTCP/VP Conversion Dist. Board
	R102-3015	Pump Module
	R102-2549	8-Station Output Module
	R89-9804	16-Sta. Surge Board. w/Switches
	R89-8589	Pump/Common Surge Board
	R102-0104	Wireline Modem (Red/Grn Lights)
	R102-0106	Radio Modem (Red/Grn Lights)
	R363-4638	Maxon Radio Transceiver
	R102-3125	Radio Adapter Board
	R35-7899	Surge Board (SPU)
OSMAC RDR	RNLN3485	Decoder Board
	R102-2012	Narrow Band RDR Decoder
	RNLN3491A	8-Station Triac Board
	R91-1303	Surge Board w/Switches
	R91-1305	Pump/Common Surge Board
E-OSMAC	R102-0187	Narrow Band Decoder Board
	R89-9449-PF	Wide Band Decoder Board
	R102-0320	Pump & Common PCB
	R102-2549	8-Station Output Module
	R89-9804	16-Sta. Surge Board. w/Switches
	R102-0318	Output Distribution PCB
	R89-9896	Earth Ground PCB
	R89-9894	24 VAC BAR PCB
VT 3	R35-1077	Timing Mechanism
VT4	R35-6220	Timing Mechanism

PRODUCT	PART #	DESCRIPTION	
Network LTC 1.0	R91-0537	Timing Mech. with Terminals	
	R91-1593	Timing Mech. w/o Terminals	
	R91-0777	Modem Board	
	R91-1303	Surge Board w/Switches	
	R91-1305	Pump/Common Surge Board	
	R91-1307	Communication Surge Board	
		R35-7899	Surge Board (SPU)
	Network LTC 2.0	R89-7169	Timing Mechanism
R89-6977		Back Plane	
R89-7170		4-Station Output Module	
R89-7171		Pump/Common Module	
R91-1307		Communication Surge Board	
R89-7519		Wireline Modem (2 Red Lights)	
R89-8453		Radio Modem (2 Red Lights)	
	R35-7899	Surge Board (SPU)	
Network LTC Plus 4.0	R102-0238	Timing Mechanism	
	R102-0681	8-Station Output Module	
	R89-8521	16-Sta. Surge Board w/Switches	
	R102-0682	Pump/Common Module	
	R102-0612	Distribution Board	
	R89-8589	Pump/Common Surge Board	
	R89-7519	Wireline Modem (2 Red Lights)	
	R89-8453	Radio Modem (2 Red Lights)	
	R35-7899	Surge Board (SPU)	
GDC 2-Wire Decoder	R102-5044	2-Wire Decoder Mother Board	
	R102-4339	2-Wire Decoder Daughter Brd.	

CONDITIONS

- Applicable tax, shipping and handling charges are extra.
- All boards are remanufactured, tested and complete. Cables, covers and connectors are not included in the board exchange and should be removed from your damaged board before it is returned to Turf Products.
- All BEP orders will have a core charge assessed for each item. A prepaid UPS shipping label is included with each order for convenient return of your damaged parts (cores). Damaged boards must be returned within 10 days to have core charge credited.
- BEP parts include a 12-month warranty The warranty is not valid for damage to equipment or exchange boards caused by lightning or electrical surges.
- Every effort will be made to have items in stock, however, this does not guarantee availability of all items at all times. Quick return of cores enables higher levels of replacement boards.