



**turf products**

**SINCE 1970**

The background of the entire page is a collage of three distinct golf course scenes. The top section shows a winter scene with snow-covered trees and a white building. The middle section shows a lush green golf course with a pond, a clubhouse, and a blue sky with white clouds. The bottom section shows a forest of trees with vibrant autumn foliage in shades of orange and red.

# IRRIGATION SERVICE PROMOTIONS

[www.turfproductscorp.com](http://www.turfproductscorp.com)

Service: (888) 442-9910 · Parts: (800) 296-7442 · Main Office: (800) 243-4355



## ON-SITE IRRIGATION SERVICE TRAINING

Let us come to you! TPC Service Technicians will provide a customized half day of training at your facility. The focus will be based on the exact irrigation equipment that you are using. Training can cover sprinkler and controller troubleshooting, wire splicing, wire tracking, along with service tips for weather stations and lightning detection systems.

**Training slots will be available from December 1 to March 24.**

**Maximum of 10 attendees** - multiple courses can be combined at one location if all using same type of irrigation equipment.

**1/2 Day On-Site Training:  
\$595.00**

*☞ Get trained the for spring, and don't pay for it until late summer.*

## CONTROL SYSTEM TUNE-UP

**Our trained Service Techs will go to your site and go through all of your Toro field controllers and central to make sure they are 100% ready for the upcoming season.**

Service Includes:

- Verify communication with the field controllers
- Measure for proper incoming and outgoing voltages
- Tighten all wire connections
- Inspect components for damage
- Test grounding
- Check all connections and re-seat cards in FIU
- Check FIU firmware version and update if necessary
- Inspect Surge Protection Unit and check connections
- Clean interior of Central computer tower

**\$75.00 Per Satellite**

**\$250.00 Per Central**

*☞ Tune-up for spring, and don't pay for it until late summer.*



## CONTROLLER MODEM TUNING



To maintain solid communication and fast downloads, TPC Service Techs can ensure that your modems meet manufacturer's specifications, eliminating surprises come spring time.

After many years in outdoor service, certify that your modems are tuned and function as they were designed.

### Option 1:

Send in or bring in your modems to our facility. Once completed, the modems will be shipped back for you to re-install. Standard UPS charges will apply.

**\$45.00 Per Modem\***

### Option 2:

A Turf Products service tech will remove and re-install all of your modems and tuning will be done at our facility. All travel and labor charges are included.

**\$80.00 Per Modem\***

*\*If a modem is unable to be tuned to meet manufacturers specifications, the per modem charge for that unit will be waived if a BEP replacement is purchased.*

## WIRE TRACKING & FAULT FINDING



Track those wires for stations that haven't worked for years or find the ground fault that constantly trips your breakers. New construction this spring? Get your wire tracked beforehand to avoid headaches later. Our Service Techs have years of experience to find your existing issues or potential problems in your wiring.

**Tracking:  
\$105.00 per hour\***

*\*Travel charge and any parts required to repair wiring issues are extra.*



## OTTERBINE FOUNTAIN MAINTENANCE



Otterbine Aerators and Fountains are the industry's leading pond management tools and can provide many years of service. The manufacturer recommends that each unit should have basic maintenance (Service Plan A) performed every three years and more advanced maintenance (Service Plan B) every 6 years. Our Certified Technicians will perform either service as requested and have your unit ready for re-installation in the spring.

### Service Plan A

- Cleaning & inspection of unit
- Oil change
- New oil plugs
- Electrical test on motor windings
- Pressure & vacuum test of motor unit

**Concept 2 or 3 (1-5hp units) Service Plan A:  
\$375.00**

### Service Plan B

- Complete teardown and cleaning of unit
- Oil Change
- New oil plugs
- Check bearing wear (replace as necessary)
- Install new seals and o-rings
- Electrical test on motor windings
- Pressure & vacuum test of motor unit

**Concept 2 or 3 (1-5hp units) Service Plan A:  
\$495.00**



**UNITS MUST BE AT OUR FACILITY  
BY MARCH 1<sup>ST</sup> TO GET  
SPECIAL SERVICE PRICING**

- Each Service Plan includes maintenance parts and labor. If bearing replacement is required, the cost of the part will be added.
- All pricing is based on customer removing unit from pond and arranging to get it back to Turf Product's facility. TPC trucking fees will be additional.
- Power cables can be tested at an additional cost if requested.

## WEATHER STATION PREVENTIVE MAINTENANCE PROGRAM

**When was the last time you thought of servicing your Campbell Scientific Weather Station? These devices require regular maintenance to ensure they work properly and provide you with accurate information.**

Our Factory-trained Service Techs will provide the following on-site service:

- Clean & inspect Temp/RH Sensor
- Clean & inspect Solar Radiation Sensor
- Clean & inspect Tipping Bucket
- Replace bearings & reed switch in Wind Sensor
- Replace RH chip in Temp/RH Sensor
- Replace Desiccant Pack
- Check communication to the central and verify correct data is being sent.

**On-Site WS Service Program:  
\$775.00**

*- Includes all labor and travel time.*



## LIGHTNING WARNING SYSTEM MAINTENANCE PROGRAM

**Make sure your lightning detection and warning system is up and ready for service during the most critical times. Whether its is a Course Alert, ESID, or Strike Guard system, our Factory-trained Service Techs will provide the following on-site service:**

- Clean & inspect each Horn Station
- Test the signal getting to each Horn Station
- Replace or add Desiccant Packs in Horn Stations
- Inspect Base Station and Main Transmitter
- Test the signal out of the Base Station to the Horns

**On-Site System Service Program:  
\$825.00**

*Includes all labor and travel time.  
Based on a maximum of 4 Horn Stations,  
Additional stations will be added at normal hourly rate.*





# Prepare now, save later.

**SAVE TIME, SAVE RESOURCES, SAVE MONEY**

Take advantage of special pricing and payment terms to stretch your budget.  
Get your in-season needs now and don't pay until the end of the season.



**turf products**  
**SINCE 1970**



## Your Trusted Partner Since 1970

Turf Products (TPC) has been providing our valued customers with the knowledge, tools and equipment to protect and preserve New England's most beautiful outdoor environments. As the exclusive representative for The Toro Company's Golf Irrigation Products and Commercial Equipment, we play a vital role in our customers success.

*Call or email Turf Products Service Department  
to schedule today*

**(888) 442-9910**

**[servicedept@turfproductscorp.com](mailto:servicedept@turfproductscorp.com)**

Service: (888) 442-9910 · Parts: (800) 296-7442 · Main Office: (800) 243-4355

**[www.turfproductscorp.com](http://www.turfproductscorp.com)**

Turf Products 157 Moody Road, Enfield, CT, 06082